

POWERBLOCK PROMAX COMMERCIAL STAND ASSEMBLY MANUAL




POWERBLOCK PROMAX COMMERCIAL STAND ASSEMBLY STEP 1

ITEM NO.	DESCRIPTION	QTY.
1	PROMAX STAND LEG WIELDMENT	2
2	PROMAX STAND BOTTOM LEG WIELDMENT	1
3	STEEL HEX HEAD SCREW, M10 X 1.5 mm THREAD, 70 mm LONG, PARTIAL THREADED	4
4	STEEL HEX NUT, M10 X 1.5 mm THREAD	4
5	STEEL WASHER FOR M10 SCREW SIZE	8

TOOLS NEEDED: TWO 17mm WRENCHES.

1. ATTACH BOTTOM TRAY (ITEM 2) TO ONE STAND LEG (ITEM 1) WITH SUPPLIED HARDWARE. DO NOT TIGHTEN HARDWARE.
2. ATTACH OTHER STAND LEG (ITEM 1) TO BOTTOM TRAY (ITEM 2) WITH SUPPLIED HARDWARE. DO NOT TIGHTEN HARDWARE. 3. TIGHTEN ALL HARDWARE.




POWERBLOCK PROMAX COMMERCIAL STAND ASSEMBLY STEP 2

ITEM NO.	DESCRIPTION	QTY.
1	PROMAX STAND LEG WIELDMENT	2
2	PROMAX STAND TOP STAND WIELDMENT	1
3	M10 - 1.5mm X 70mm HEX HEAD BOLT	4
4	STEEL HEX NUT, M10 X 1.5 mm THREAD	4
5	STEEL WASHER FOR M10 SCREW SIZE	8

TOOLS NEEDED: TWO 17mm WRENCHES.

1. ATTACH TOP TRAY (ITEM 2) TO ONE STAND LEG (ITEM 1) WITH SUPPLIED HARDWARE. DO NOT TIGHTEN HARDWARE.
2. ATTACH OTHER STAND LEG (ITEM 1) TO TOP TRAY (ITEM 2) WITH SUPPLIED HARDWARE. DO NOT TIGHTEN HARDWARE.
3. TIGHTEN ALL HARDWARE.



POWERBLOCK PRO MAX COMMERCIAL STAND ASSEMBLY STEP 3

ITEM NO.	DESCRIPTION	QTY.
1	PROMAX STAND	2
2	PROMAX STAND CASTERS	1
3	STEEL HEX HEAD SCREW, M8 X 1.25 mm THREAD, 20 mm LONG	4
4	STEEL HEX NUT, M8 X 1.25 mm THREAD	4
5	STEEL WASHER FOR M8 SCREW SIZE	8

TOOLS NEEDED: TWO 13mm WRENCHES.

1. ATTACH CASTERS (ITEM 2) TO STAND (ITEM 1) WITH SUPPLIED HARDWARE. TIGHTEN HARDWARE.
2. ATTACH CASTERS WITH BRAKE (ITEM 3) TO STAND (ITEM 1) WITH SUPPLIED HARDWARE.
3. TIGHTEN HARDWARE.

