

POWERBLOCK PROMAX STAND ASSEMBLY INSTRUCTIONS




POWERBLOCK PROMAX STAND

ASSEMBLY STEP 1

ITEM NO.	DESCRIPTION	QTY.
1	PROMAX STAND LEG WELDMENT	2
2	PROMAX STAND BOTTOM TRAY WELDMENT	1
3	STEEL HEX HEAD SCREW, M10 X 1.5 mm THREAD, 70 mm LONG, PARTIAL THREADED	4
4	STEEL HEX NUT, M10 X 1.5 mm THREAD	4
5	STEEL WASHER FOR M10 SCREW SIZE	8

TOOLS NEEDED: TWO 17mm WRENCHES.

1. ATTACH BOTTOM TRAY (ITEM 2) TO ONE STAND LEG (ITEM 1) WITH SUPPLIED HARDWARE.
DO NOT TIGHTEN HARDWARE.
2. ATTACH OTHER STAND LEG (ITEM 1) TO BOTTOM TRAY (ITEM 2) WITH SUPPLIED HARDWARE.
DO NOT TIGHTEN HARDWARE.
3. TIGHTEN ALL HARDWARE.




POWERBLOCK PROMAX STAND

ASSEMBLY STEP 2

ITEM NO.	DESCRIPTION	QTY.
1	PROMAX STAND LEG WELDMENT	2
2	PROMAX STAND TOP TRAY WELDMENT	1
3	STEEL HEX HEAD SCREW, M10 X 1.5 mm THREAD, 70 mm LONG, PARTIAL THREADED	4
4	STEEL HEX NUT, M10 X 1.5 mm THREAD	4
5	STEEL WASHER FOR M10 SCREW SIZE	8

TOOLS NEEDED: TWO 17mm WRENCHES.

1. ATTACH TOP TRAY (ITEM 2) TO ONE STAND LEG (ITEM 1) WITH SUPPLIED HARDWARE.
DO NOT TIGHTEN HARDWARE.
2. ATTACH OTHER STAND LEG (ITEM 1) TO TOP TRAY (ITEM 2) WITH SUPPLIED HARDWARE.
DO NOT TIGHTEN HARDWARE.
3. TIGHTEN ALL HARDWARE.



POWERBLOCK PROMAX STAND

ASSEMBLY STEP 3

ITEM NO.	DESCRIPTION	QTY.
1	PROMAX STAND	1
2	PROMAX STAND CASTERS	2
3	PROMAX STAND CASTERS WITH BRAKE	2
4	STEEL HEX HEAD SCREW, M8 X 1.25 mm THREAD, 20 mm LONG	16
5	STEEL HEX NUT, M8 X 1.25 mm THREAD	16
6	STEEL WASHER FOR M8 SCREW SIZE	32

TOOLS NEEDED: TWO 13mm WRENCHES.

1. ATTACH CASTERS (ITEM 2) TO STAND (ITEM 1) WITH SUPPLIED HARDWARE.
TIGHTEN HARDWARE.
2. ATTACH CASTERS WITH BRAKE (ITEM 3) TO STAND (ITEM 1) WITH SUPPLIED HARDWARE.
TIGHTEN HARDWARE.

